





GOV DOC BRA 138



EVALUATION OF CITY OF BOSTON PARK AND RECREATION LAND

NEIGHBORHOOD OF NORTH DORCHESTER

Prepared for

MAYOR'S OFFICE OF CAPITAL PLANNING

Do Not

THE HALMORSON COMPANY, INC. IANDSCAFE ARCHITECIS AND SITE PIANNING CONSULTANTS 161 MASSACHUSETTS AVENUE BOSTON, MASSACHUSETTS 02115



JON 16 451

EVALUATION OF CITY OF BOSTON PARK AND RECREATION LAND

NEIGHBORHOOD OF NORTH DORCHESTER

Prepared for

MAYOR'S OFFICE OF CAPITAL PLANNING

THE HALVORSON COMPANY, INC. LANDSCAPE ARCHITECTS AND SITE PLANNING CONSULTANTS 161 MASSACHUSETTS AVENUE BOSTON, MASSACHUSETTS 02115

15.4 Mig. a (त्रुर्ग 32 h-es pro-

TABLE OF CONTENTS

NEIGHBORHOOD OF NORTH DORCHESTER

PARKS		Acreage		
ND-1.	Allen Park Adams, Winter and Church Streets	1.29		
ND 4.*	Carson Street Playground	D.		
ND-3.**	Columbia Point Playground	33.29		
ND-4.	Deer Street Park Deer Street	0.2		
ND-5.	Downer Avenue Playground Downer Avenue	0.78		
ND-6.	McConnell Park Springdale Street opposite Playstead Road	6.2 A		
ND-7.	Not Within Scope of Survey			
ND-8.	Quincy Street Play Area Quincy and Stanley Streets	0.38		
ND-9.	Ryan Play Area Harbor View Street and Dorchester Avenue	0.64		
ND-10.	Savin Hill Park Grampian and Alpine Ways	8.26		
ND-11 1	ND-14. Not Within Scope of Survey			
SOUARES AN	Acreage			
ND-15.	Coppens Square Bowdoin, Adams and Church Streets	0.3		

ND-16. - ND-44. Not Within Scope of Survey


^{*} This site no longer exists.
** This site is being redeveloped as housing.




Neighborhood: North Dorcester
Map of Neighborhood's Open Space

(Sp) Dorcester

:









CITY OF BOSTON PARK EVALUATION



Neighborhood: North Dozchester	SITE NO.
Site Name: AUEN PARK	Site Type: Save
Location: ADAMS, WINTER CHURCH	Acreage: 1.29A
Evaluation Team: SF 3Pott	Weather Conditions:
Evaluation Date: 5.7.87	Sunny
Surrounding Land Uses: Residen	hal. Church.

Site Plan ZESIDENTIAL Church Street Monument houmant ?







Site Photograph 1

View along main access into park from the corner of Adams and Church Streets with planting of Norway Maples. Water fountain given prominent location.



Site Photograph 2

View showing civil war monument and historic meeting house steeple aligned - a view not emphasized by current pedestrian circulation layout.



Site Photograph 3

View downhill showing seating and shade trees along access route.








Site Photograph 4

Civil war monument presence as a point of historic and focal importance could be strengthened.



Site Photograph 5

Grass and weed control around monument fence could be improved.



Site Photograph 6

View into park from corner of Adams and Winter Streets entrance into park and edges need to be made stronger.



Site Name: Allen Park
Location: Adams Winter and Church Streets

Location: Adams, Winter and Church Streets Acreage: 1.29 A Site Type: Square

Site Description:

Allen Park is a triangular site located at the high point of this North Dorchester area. The site slopes down from the old Dorchester Meeting House. It is enclosed by Adams, Winter and Church Streets, and it functions like a town common. Its simple design of grass, trees, paths and benches is very appropriate to this function. There is a partial allee of Norway Maples planted along part of the central pathway. A few other trees are located in the upper area of the green. The park is highlighted by a civil War morument. Residential and institutional uses surround the site.

No.: ND-1

Condition Assessments:

Most standard park built elements are in good condition. Only one bench is in fair condition. Unfortunately, graffiti lends a deteriorated character to the park. The tree plantings are in fair condition. The most recent planting of Norway Maples along the central path appear to be growing poorly. Although they have sustained trunk damage, there is most likely another cause for their lack of vigor. Numerous rock outcroppings on the site suggest that shallow soil and consequent dryness may be a factor. The turf is in fair to good condition, although not well maintained. There are several barren areas in the lawn.

Major Site Issues:

Allen Park has great potential to serve the function of a rich green central common for this neighborhood. In order to do this more successfully, however, its primary elements of trees, pathways and monument need to be used more effectively. The overall appearance of the site is exposed and barrien, and there needs to be a stronger planting of trees. Use of Norway Maples and Lindens should be avoided in favor of trees that are less used in the urban street environment and convey a more park-like character. Trees should be used that can survive in the soil conditions of the site. Planting should also seek to strengthen the park entrances.

The monument is an important focal point of historic interest to the site, and should be



Site Name: Allen Park Location: Adams, Winter and Church Streets

Acreage: 1.29 A Site Type: Square

...

Site Description:

Allen Park is a triangular site located at the high point of this North Dorchester area. The site slopes down from the old Dorchester Meeting House. It is enclosed by Adams, Winter and Church Streets, and it functions like a town common. Its simple design of grass, trees, paths and benches is very appropriate to this function. There is a partial allee of Norway maples planted along part of the central pathway. A few other trees are located in the upper area of the green. The park is highlighted by a Civil War monument. Residential and institutional uses surround the site.

Condition Assessments:

Most standard park-built elements are in good condition. Only one bench is in fair condition. Unfortunately, graffiti lends a deteriorated character to the park. The tree plantings are in fair condition. The most recent planting of Norway maples along the central path appear to be growing poorly. Although they have sustained trunk damage, there is most likely another cause for their lack of vigor. Numerous rock outcroppings on the site suggest that shallow soil and consequent dryness may be a factor. The turf is in fair to good condition, although not well maintained. There are several barren areas in the lawn.

Major Site Issues:

Allen Park has great potential to serve the function of a rich green central common for this neighborhood. In order to do this more successfully, however, its primary elements of trees, pathways and monument need to be used more effectively. The overall appearance of the site is exposed and barren, and there needs to be a stronger planting of trees. Use of Norway maples and lindens should be avoided in favor of trees that are less used in the urban street environment and convey a more park-like character. Trees should be used that can survive in the soil conditions of the site. Planting should also seek to strengthen the park entrances.

The monument is an important focal point of historic interest to the site, and should be incorporated into the path system. At present, pathways pass close by but do not embrace it.

Improved maintenance, particularly of the lawn, which is another key element of the space, would greatly enhance its presence on the street.



Site Name: Allen Park

Location: Adams, Winter and Church Streets

Acreage: 1.29 A Site Type: Square

,0

Site Description:

Allen Park is a triangular site located at the high point of this North Dorchester area. The site slopes down from the old Dorchester Meeting House. It is enclosed by Adams, Winter and Church Streets, and it functions like a town common. Its simple design of grass, trees, paths and benches is very appropriate to this function. There is a partial allee of Norway maples planted along part of the central pathway. A few other trees are located in the upper area of the green. The park is highlighted by a Civil War monument. Residential and institutional uses surround the site.

Condition Assessments:


Most standard park-built elements are in good condition. Only one bench is in fair condition. Unfortunately, graffiti lends a deteriorated character to the park. The tree plantings are in fair condition. The most recent planting of Norway maples along the central path appear to be growing poorly. Although they have sustained trunk damage, there is most likely another cause for their lack of vigor. Numerous rock outcroppings on the site suggest that shallow soil and consequent dryness may be a factor. The turf is in fair to good condition, although not well maintained. There are several barren areas in the lawn.

Major Site Issues:

Allen Park has great potential to serve the function of a rich green central common for this neighborhood. In order to do this more successfully, however, its primary elements of trees, pathways and monument need to be used more effectively. The overall appearance of the site is exposed and barren, and there needs to be a stronger planting of trees. Use of Norway maples and lindens should be avoided in favor of trees that are less used in the urban street environment and convey a more park-like character. Trees should be used that can survive in the soil conditions of the site. Planting should also seek to strengthen the park entrances.

The monument is an important focal point of historic interest to the site, and should be incorporated into the path system. At present, pathways pass close by but do not embrace it.

Improved maintenance, particularly of the lawn, which is another key element of the space, would greatly enhance its presence on the street.



Site Name: Allen Park

Location: Adams, Winter and Church Streets Acreage: 1.29 A Site Type: Square

Site Description:

Allen Park is a triangular site located at the high point of this North Dorchester area. The site slopes down from the old Dorchester Meeting House. It is enclosed by Adams, Winter and Church Streets, and it functions like a town common. Its simple design of grass, trees, paths and benches is very appropriate to this function. There is a partial allee of Norway Maples planted along part of the central pathway. A few other trees are located in the upper area of the green. The park is highlighted by a Civil War monument. Residential and institutional uses surround the site.

No.: ND-1

Condition Assessments:

Most standard park built elements are in good condition. Only one bench is in fair condition. Unfortunately, graffiti lends a deteriorated character to the park. The tree plantings are in fair condition. The most recent planting of Norway Maples along the central path appear to be growing poorly. Although they have sustained trunk damage, there is most likely another cause for their lack of vigor. Numerous rock outcroppings on the site suggest that shallow soil and consequent dryness may be a factor. The turf is in fair to good condition, although not well maintained. There are several barren areas in the lawn.

Major Site Issues:

Allen Park has great potential to serve the function of a rich green central common for this neighborhood. In order to do this more successfully, however, its primary elements of trees, pathways and monument need to be used more effectively. The overall appearance of the site is exposed and barren, and there needs to be a stronger planting of trees. Use of Norway Maples and Lindens should be avoided in favor of trees that are less used in the urban street environment and convey a more park-like character. Trees should be used that can survive in the soil conditions of the site. Planting should also seek to strengthen the park entrances.

The monument is an important focal point of historic interest to the site, and should be incorporated into the path system. At present,



- - A 1 "

Improved maintenance, particularly of the lawn which is another key element of the space, would greatly enhance its presence on the street.



CITY OF BOSTON


CITY OF BOSTON PARK EVALUATION														SITE SUMMARY				SITE NO.			
1 simple regported to pasted than need: - thouse ofte.	AYOUT/ORGANIZATION OF SPACE (Albumbant hit healed as a major heal point of fook. Thursh,	Unidor URage a tree plantings		autoants an smeet eagle ? access good brought, site	adaque		graph, demobilised anches,	Mo.		2005	1000	Nave.			renduce, pavement, himmond good ting the				meadaing suppossingly poorly - pertiago: breader soil this	her site issues: Let to the duplet side fletc howing as a final point, habit cother less exching design and interprete it mas. Monument necks cleaving the secret planting if these	Law Han to and per - to hade be proved moving. 110 Law Han to and enter the most confine and around around the es head to be employed and - planting, Ance and Borsuluss, etc.
IGN CONSIDERATIONS:	AYOUT/ORGANIZATION OF SPACE	SE OF PLANT MATERIALS	PPROPRIATENESS OF PARK UNCTIONS TO NEIGHBORHOOD	ARRIER FREE DESIGN	RAINAGE CONDITION	ESIGN-RELATED AINTENANCE ISSUES	ANDALISM	ANT PARCEL TO SOUTH, EAST	IBILITY AND SAFETY:	ISIBILITY INTO SPACE	ISIBILITY OUT FROM SPACE	IDDEN CORNERS IN SPACE		DITION ASSESSMENTS:	TANDARD PARK BUILT ELEMENTS	PORTS FACILITIES	LAYGROUNDS	UILDINGS	ATURAL PARK ELEMENTS	Lette issues: Lette in the layout site flep Is exchine closique and inch Alonancia (rects closining)	Law Arm Figure The his his actions of the property of the pro





CITY OF BOSTON PARK EVALUATION


STANDARD PARK BUILT ELEMENTS













BUILDINGS AND PLAYGROUNDS CITY OF BOSTON PARK EVALUATION ACCESS, CIRCULATION AND PARKING SITE NO. ACCESS CONDITION RGANIZATION MATERIALS MATERIALS CUANTITY ACCESS CONTROL: My cuts PEDESTRIAN CIRCULATION VEHICULAR CIRCULATION (GENERAL) MAINTENANCE ACCESS PEDESTRIAN ACCESS AGE DISTRIBUTION VEHICULAR ACCESS LAYGROUNDS ECREATION QUIPMENT: ESTROOM FENCING TORAGE URFACE DCING THER




NATURAL PARK ELEMENTS



			٦	UANTITY		CONDITION	NO	LOCA	LOCATION MISC.
		1	100	14000 V			CONSTR	W.S.	
	1	300	3 2 2 2	WELVE PR	TO SAID	IF THE			
REES	X	1 X	31	119		X		X	-damage at hase
HRUBS	Ţ							-	P
URF	X			27	-a	1	1		anday play wanter but patch
ROUNDCOVER								-	
LOWER BEDS									
GROUND									
CONTAINER	1								
EED SPECIES	I								
saoo	I								
ONDS									
TREAMS	1								
PECIAL ECOLOGICAL	I							H	
-									










Neighborhood: North Dorchestel
Site Name: Countie Prod.
Location: Montice Acreage: 33.29A

Evaluation Team: # 78# Weather Conditions:
Evaluation Date: 6:267
Surrounding Land Uses: Residental

Site Plan
















Site no longer a park.



Site Photograph 2



Site Photograph 3








Site Photograph 4



Site Photograph 5



Site Photograph 6



Neighborhood: North Dorchester

Site Name: Columbia Point Playground

Location: Monticello Avenue

Acreage: 33.29 A Site Type: Playfield

Site Description:

Columbia Point Playground is a large irregularly shaped area along the north shore of the Columbia Point peninsula. At present the site is entirely under

construction formew housing development. All structures will be demolished in

the course of the present undertaking.

Major Site Issues:

Location of future park facilities is part of the over-all master plan for the renovation of Columbia Point.

UR



DRAFT

Neighborhood: North Dorchester

Site Name: Columbia Point Playground No.: ND-3

Location: Monticello Avenue

Acreage: 33.29 A Site Type: Playfield

Site Description: Columbia Point Playground is a large irregularly


shaped area along the north shore of the Columbia Point peninsula. At present the site is entirely under construction for new housing development. All structures will be demolished in the course

of the present undertaking.

Major Site Issues: Location of future park facilities is part of the

over-all master plan for the renovation of


Columbia Point.



SITE SUMMARY




==	_			=-	=	-	==		_			_	_		-					
																				The ode is in the prices of volume word as verdontial housing
ESIGN CONSIDERATIONS:	LAYOUT/ORGANIZATION OF SPACE	USE OF PLANT MATERIALS	APPROPRIATENESS OF PARK FUNCTIONS TO NEIGHBORHOOD	BARRIER FREE DESIGN	DRAINAGE CONDITION	DESIGN-RELATED MAINTENANCE ISSUES	VANDALISM	JACANT PARCEL TO SOUTH, EAST	ISIBILITY AND SAFETY:	VISIBILITY INTO SPACE	VISIBILITY OUT FROM SPACE	HIDDEN CORNERS IN SPACE		ONDITION ASSESSMENTS:	STANDARD PARK BUILT ELEMENTS	SPORTS FACILITIES	PLAYGROUNDS	BUILDINGS	NATURAL PARK ELEMENTS	TWE GRE IS IN THE




STANDARD PARK BUILT ELEMENTS




S




S




p.7 CITY OF BOSTON PARK EVALUATION SPORTS FACILITIES SITE NO. MISC. LOCATION CONDITION MATERIALS YT I TNAUC BACKBOARD/HOOP FOOTBALL: FIELD LITTLE LEAGUE: SOCCER: FIELD BASKETBALL: BANGBOARD NET POLES OUTFIELD OUTFIELD OUTFIELD BACKSTOP BACKSTOP BACKSTOP FENCING SURFACE INFIELD INFIELD SURFACE BASEBALL: INFIELD SOFTBALL: TENNIS: OTHER OTHER SCHEE COURTS FIFTHS







NATURAL PARK ELEMENTS














Neighborhood: North Dorchester	SITE NO
Site Name: Deze Stever Frek	Site Type:
Location: Dere	Acreage: O.ZA
Evaluation Team: SF 48H	Weather Conditions:
Evaluation Date: 5 11-37	Surm
Surrounding Land Uses: Resident	hal
Colonel Daivel	
Site Plan Maw Bys 76	omlis Club
Dorchester	Avenue
Pleasant Stre	Deery Street Boach Street
Idarel Dan Bys & Girl	iel Marry Schub








Site Photograph 1

Playground constructed by adjacent Marr Boys and Girls Club.



Site Photograph 2

Timber edge to tree planting creates difficult to maintain grass strip.



Site Photograph 3



Neighborhood: North Dorchester

Site Name: Deer Street Park Location: Deer Street Acreage: 0.2A Site Type: Playlot

Site Description:


Deer Street Park is a small rectangular site located on the west side of Deer Street. To the north the site abuts the Colonel Daniel Marr Boys and Girls Club, to the south a parking lot, and to the west residences. Enclosed with a four-foot chain-link fence, the park has a large metal and wood play structure enclosed with a timber edge and a bituminous concrete path. Surrounding the play area is a strip of grass with several trees. The western edge of the park is a moderately steep grassy slope.

Condition Assessments:

The improvements to this park are recently constructed and all are in good to excellent condition, except plantings. About half the trees have died. The remaining trees are in fair condition. The recently installed sod is under heavy use and is starting to fail.

Major Site Issues:

Improvements to Deer Street Park were constructed and are maintained by the Boys and Girls Club. The design of the park has several shortcomings. The grass strip will very likely be worn out by children's play. The grass in the area along Deer Street would survive better if the fence was adjacent to the sidewalk bordering the play structure, thereby separating the grass and trees from active use. This would best support growth, and provide shade and a pleasant green space along the edge of the play area. The grass slope on the west side of the park will probably be worn out by play as well. A low retaining wall or some other means of controlling access to this area would be desirable.



DRAT

Neighborhood: North Dorchester Site Name: Deer Street Park

Location: Deer Street

Acreage: 0.2 A Site Type: Playlot No.: ND-4

Site Description:

Deer Street Park is a small rectangular site located on the west side of Deer Street. To the north the site abuts the Colonel Daniel Marr Boys and Girls Club, to the south a parking lot and to the west residences. The park is enclosed with a four foot chain link fence. The park has a large metal and wood play structure enclosed with a timber edge and a bituminous concrete path. Surrounding the play area is a strip of grass with several trees. The western edge of the park is a moderately steep grassed slope.


Condition Assessments:

The improvements to this park are recently constructed and all are in good to excellent condition except for plantings. About half the trees have died. The remaining trees are in fair condition. The recently installed sod is under heavy use and is starting to fail.

Major Site Issues:

Improvements to Deer Park were constructed and are maintained by the Boys and Girls Club. The design of the park has several shortcomings. The grass strip will very likely be worn out by children's play. The grass in the area along Deer Street would better survive if the fence was adjacent to the sidewalk bordering the play structure, thereby separating the grass and trees from active use. This would best support growth, provide shade and a pleasant green space along the edge of the play area. The grass slope on the west side of the park will most likely be worn out by play as well. A low retaining wall or some other means of controlling access to this

area would be desirable.




ITY OF BOSTON

MMARY

P.5 ND SITE NO.


IGN CONSIDERATIONS:		F
AVOIT /OBCANIZATION OF SPACE	water of love and Street of course of our area and Dear	A
SE OF PLANT MATERIALS	sheet excellen a meentenance problem need due , ist mother me planting	F
PPROPRIATENESS OF PARK UNCTIONS TO NEIGHBORHOOD	- Trees not and weaked, Gran bash the sicep.	KK
ARRIER FREE DESIGN	705	
RAINAGE CONDITION	adequate.	E
ESIGN-RELATED AINTENANCE ISSUES	the tunion planting taked is becaked in the centur of a strip of grass	V
ANDALISM	HIM blocking Houry.	Α
ANT PARCEL TO SOUTH, EAST		I
IBILITY AND SAFETY:		J.
ISIBILITY INTO SPACE	pars	<u>JA</u>
ISIBILITY OUT FROM SPACE	purs	Ľ
IDDEN CORNERS IN SPACE	Nord.	I.
		0
DITION ASSESSMENTS:		N
TANDARD PARK BUILT ELEMENTS	evellor	
PORTS FACILITIES		
LAYGROUNDS	excellet.	
UILDINGS		S
ATURAL PARK ELEMENTS	Pair to pair: There are ender sticky; grass seed in waring and under	ITE
MARY SITE ISSUES:	, the	SUN


Powting lethist aid not well support the growth and electer extra maintenary This park has been improved and is maintained by coloured Dissiel Marr Pays and Girls Clast,



STANDARD PARK BUILT ELEMENTS









SPORTS FACILITIES








BUILDINGS AND PI.AYGROUNDS CITY OF BOSTON PARK EVALUATION ACCESS, CIRCULATION AND PARKING SITE NO. PARKING CONDITION MATERIALS MATERIALS CUANTITY *EDESTRIAN CIRCULATION PEHICULAR CIRCULATION PLAYGROUNDS (GENERAL) believe MAINTENANCE ACCESS PEDESTRIAN ACCESS AGE DISTRIBUTION: VEHICULAR ACCESS ACCESS CONTROL: EQUIPMENT: RECREATION RESTROOM STORAGE SURFACE FENCING EDGING OTHER





NATURAL PARK ELEMENTS














Neighborhood: Norm Dorchester
Site Name: Downer Avenue Plod.
Location: Downer Avenue Plod.
Location: Downer Acreage: 0.78 A

Evaluation Team: F + B# Weather Conditions:
Evaluation Date: 5.11.67.
Surrounding Land Uses:









Site Photograph 1

Desire lines from adjacent property a short cut through the site. Granite pieces stock piled on site - difficult to maintain grass around them.




Site Photograph 2

Dumping of brush and other debris.



Site Photograph 3


Chain link pulled down to allow access through. Fence posts bent. No hoop on basketball court.





Site Photograph 4

Main access from Downer Avenue with view through to scenic overlook structure. Granite pieces used as access control.




Site Photograph 5

Fencing missing steep slope below a safety problem.



Site Photograph 6

Scenic overlook - a hidden corner. Graffiti, concrete spalling.








Site Photograph 7

Playground - safety surface encroached by grass and weeds. Equipment vandalised.




Site Photograph 8

Masonry wall and vegetation growth prevents visual access into site.



Site Photograph 9

View into site from adjacent stairs. Fence unnecessary along top of wall. Barbed wire present in some areas.



Neighborhood: North Dorchester

Site Name: Downer Avenue Playground

Location: Downer Avenue

Acreage: 0.78 A Site Type: Playlot

Site Description:

Downer Avenue Playground is a long rectangular park on the south side of Downer Avenue. The southern edge of the park abuts a very steep slope falling off to the Public Works Department storage yard. To the east and west the park abuts residences. On the western edge of the park is a very long set of concrete and stone stairs providing access to Hancock Street from Downer Avenue. There is a six-foot cobblestone wall topped by a five-foot chain-link fence with barbed wire along the north park edge. The main access to the park leads from Downer Avenue to a concrete overlook with high chain-link fencing. To the east of the entry walk is a basketball court. To the west is a playground. Trees frame the park around its edges. Surrounding land uses are residential and municipal.


Condition Assessments:

The standard park-built elements are in fair to poor condition. The basketball court is unusable because there are no rims. The playground is barely functional, badly overgrown with vegetation and vandalized. The trees are mostly in good condition. The grass is in very poor condition. Renovations to the park are scheduled by the city.

Major Site Issues:

Lack of maintenance and vandalism have combined to make Downer Avenue Playground appear abandoned and extremely deteriorated. This appearance is aggravated by high chain-link fencing and barbed wire along Downer Avenue. The concrete overlook is massive and imposing, and chain-link fencing is missing along one edge.

Access to the Public Works Department storage yard needs to be better controlled, and improvements along the boundary between the park and yard are needed. One entrance into the park appears insufficient, and additional entrances should be developed which respond to desired access points.





No.: ND-5

Neighborhood: North Dorchester

Site Name: Downer Avenue Playground

Location: Downer Avenue

Acreage: 0.78 A Site Type: Playlot

Site Description:

Downer Avenue Playground is a long rectangular park on the south side of Downer Avenue. The southern edge of the park abuts a very steep slope falling off to the Public Works Department storage yard. To the east and west the park abuts residences. On the western edge of the park is a very long set of concrete and stone stairs providing access to Hancock Street from Downer Avenue. There is a six foot cobblestone wall topped by a five foot chain link fence with barbed wire along the north park edge. The main access to the park leads from Downer Avenue to a concrete overlook with high chain link fencing. To the east of the entry walk is a basketball court. To the west is a playground. Trees frame the park around its edges. Surrounding land uses are residential and municipal.


Condition Assessments:

The standard park built elements are in fair to poor condition. The basketball court is unusable because there are no rims. The playground is badly overgrown with vegetation, vandalized and functions very minimally. The trees are mostly in good condition. The grass is in very poor condition. Renovations to the park are scheduled by the City.

Major Site Issues:

Lack of maintenance and vandalism have combined to make Downer Avenue Playground appear abandoned and in an extremely deteriorated state. This appearance is aggravated by high chain link fencing and barbed wire along Downer Avenue. The concrete overlook is massive and imposing, and chain link fencing is missing along one edge.


Access to the Public Works Department storage yard needs to be better controlled, and improvements along the boundary between the park and yard coordinated between the two City departments. One entrance into the park appears insufficient, and additional entrances should be developed which respond to desired access points.



CITY OF BOSTON





P	Ā	R	K		Đ	V	A	L	ŭ	ĪA	I	'I	0	N				S	ITE	SUMMARY	ND 5
DillABili office 1 attain traint - (MCALO.	Tusternal I blan and other, at the of site, some onertook I	- 🔾		مكا	alagente		grapht, privilentendees; highes, lane pulled down in avode	Non		Novypour due to plant growth above strail edge theills around botont	100 J	In wredged areas ? enceased belont.			Fonce, will lendles fair to poor	Thurstethall court par, & Mohwops	barely usable; - valdation, 7 moans of plant growth.		WILL 7 Overshaws.	IMARY SITE ISSUES: Lack of Manuferance over along from of of thise has allowed this park to become ontremy over or now higher of purely function to the form. Variabling afficients park of wine along others expensely and laring the along others and laring the form. In an lank force and laring the following of the force.	assure and under your fundate. — only one incomparts at the fact the colloquest of determined and
SIGN CONSIDERATIONS:	LAYOUT/ORGANIZATION OF SPACE	USE OF PLANT MATERIALS	APPROPRIATENESS OF PARK FUNCTIONS TO NEIGHBORHOOD	BARRIER FREE DESIGN	DRAINAGE CONDITION	DESIGN-RELATED MAINTENANCE ISSUES	VANDALISM	ACANT PARCEL TO SOUTH, EAST	SIBILITY AND SAFETY:	VISIBILITY INTO SPACE	VISIBILITY OUT FROM SPACE	HIDDEN CORNERS IN SPACE		NDITION ASSESSMENTS:	STANDARD PARK BUILT ELEMENTS	SPORTS FACILITIES,	PLAYGROUNDS	BUILDINGS	NATURAL PARK ELEMENTS	Lack of Manuferance of Manuferance of Manuferance of Year and of the Manuferance of Manuferance	Sent operate 15 M Dought annichtorie Faring along star



STANDARD PARK BUILT ELEMENTS








CITY OF BOSTON SPORTS FACILITIES SITE NO MISC. CONDITION MATERIALS QUANTITY BACK BOARD / HOOP FOOTBALL: FIELD LITTLE LEAGUE: SOCCER: FIELD BANGBOARD NET POLES BASKETBALL: BACKSTOP OUTFIELD BACKSTOP OUTFIELD OUTFIELD BACKSTOP FENCING INFIELD SURFACE SURFACE INFIELD INFIELD BASEBALL: SOFTBALL: TENNIS:








NATURAL PARK ELEMENTS



	ouded construct							we we			
	remon some has to previde its crouded conditions	Shrubs	mountains!					rank and grower Mound up front			
LOCATION MISC.	remore Sa	natured shorter	totally unmanitaries					ranh wer			
CONDITTION CONDITION	X	X									
AUANTITY PARTITY STATES OF STATES O	0108X 02X	×	X					X			
		S		DCOVER	R BEDS	UND	TAINER	SPECIES		MS	AL ECOLOGICAL RE/AREA









Neighborhood: Nath Doubester

Site Name: National Park

Location: Spendage

Evaluation Team: Style


Evaluation Date: 5.7.67


Site Type: Style

Acreage: 57-16 Style

Weather Conditions:


Summy







Percolation of sports field poor ponding of water.




Site Photograph 2


View along inside edge by Springdale Street poor grass growth. Use of enclosed area unclear.




Site Photograph 3

View across ballfield shows patchy grass and proximity of site to expressway.





View showing sidewalk along beachfront and play equipment area.




Site Photograph 5

Parking along edge of playground. Boulders used as access control. Note weed growth along base of fence, contributes to unkempt appearance of park.




Site Photograph 6

Timber play structures poor safety surface. Many broken or missing parts make structures almost unusable.







View of monument from beach - steps spalling and invaded by weeds. Plaque missing from monument.




Site Photograph 8

Poor grass growth - note broken glass. Need for access control on right along parking edge.



Site Photograph 9

Pedestrian access from Denny Street. Trees growing well in grassed area.



Neighborhood: North Dorchester

Site Name: McConnell Park

Location: Springdale Street and Playstead Road

Acreage: 6.2 A Site Type: Playfield

a manifestation of

Site Description:


McConnell Park is a large active recreational park with baseball, softball, and I ittle I rague fields located between the Southeast Expressway on the west and the Savin Hill Beach on the south. To the east there is a parking area surrounding a cul-du-sac with the residential areas of Savin Hill to the north and east. The ballfield area has a linear planting of Norway maples along the east and south edges. Between the parking area and the water is a large playground with sitting areas. There is a stone monument surrounded by a metal fence.

Condition Assessments:

Most of the standard park-built elements are in fair to good condition. The playing fields are in fair to poor condition. There are depressions where water ponds. Percolation through the soil is poor and the grass is badly worn in areas. The tree plantings are in generally good condition. The playground varies in condition. The concrete structures are in good condition. However, they have low play value. Most of the swings are broken. The mulched play surface is in poor condition and full of glass. The concrete surface is in fair condition, but is not an appropriate surface for play. Renovations to the ballfields, playground and sitting area by the monument are planned by the City.

Major Site Issues:

The general layout of facilities in McConnell Park is good. However, the parking area around the cul-du-sac needs organization and vehicular access control needs to be established to prevent cars from entering the site. The major issue for the site is the condition of ballfields and playground. Both of these will be addressed in the scheduled renovations. When this is completed, it is important that the park receive higher levels of maintenance than it does at present, to prevent a repeated cycle of deterioration.



Neighborhood: North Dorchester Site Name: McConnell Park

Location: Springdale Street and Playstead Road

Acreage: 57-1-7 Site Type: Playfield 0. - E

Site Description:

McConnell Park is a large active recreational park with baseball, softball, and little league fields located between the Southeast Expressway on the west and the Savin Hill Beach on the south. To the east there is a parking area surrounding a cul-du-sac with the residential areas of Savin Hill to the north and east. The ballfield area has a linear planting of Norway Maples along the east and south edges. Between the parking area and the water is a large playground with sitting areas. There is a stone monument surrounded by a metal fence.


No.: ND-6

Condition Assessments:

Most of the standard park built elements are in fair to good condition. The playing fields are in fair to poor condition. There are depressions where water ponds. Percolation through the soil is poor and the grass is badly worn in areas. The tree plantings are in generally good condition. The playground varies in condition. The concrete structures are in good condition. However, they have low play value. Most of the swings are broken. The mulched play surface is in poor condition and full of glass. The concrete surface is in fair condition, however, is not an appropriate surface for play. Renovations to the ballfields, playground and sitting area by the monument are planned by the City.

Major Site Issues:


The general layout of facilities in McConnell Park is good. However, the parking area around the cul-du-sac needs organization and vehicular access control needs to be established to prevent cars from entering the site. The major issue for the site is the condition of ballfields and playground. Both of these will be addressed in the scheduled renovations. When this is completed, it is important that the park receive higher levels of maintenance than it does at present, to prevent a repeated cycle of deterioration.



SITE SUMMARY





DESIGN CONSIDERATIONS:	Was along but had; but it is the way in the
LAYOUT/ORGANIZATION OF SPACE	Cash it a si Della Distance
USE OF PLANT MATERIALS	J. 10 14: 11. 21. 3
APPROPRIATENESS OF PARK FUNCTIONS TO NEIGHBORHOOD	
BARRIER FREE DESIGN	No aubud how dest
DRAINAGE CONDITION	Date 1/1 - 20 11, 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
DESIGN-RELATED MAINTENANCE ISSUES	in a di part portine mitalia for e hal or low a tropia
VANDALISM	Int. April quality health
VACANT PARCEL TO SOUTH, EAST	
VISIBILITY AND SAFETY:	
VISIBILITY INTO SPACE	
VISIBILITY OUT FROM SPACE	
HIDDEN CORNERS IN SPACE	$^{\prime}$
CONDITION ASSESSMENTS:	
STANDARD PARK BUILT ELEMENTS	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
SPORTS FACILITIES	Get ex 196 to the inche content of wards.
PLAYGROUNDS	Or to go letter out good by the Spicetimes for a diameter orally
-BUILDINGS-	John With and minimedly face in
NATURAL PARK ELEMENTS	The part of the contract law sign of lead or fire
PRIMARY SITE ISSUES:	
1000	The College of
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	the state of the s
1	The transmitted of the state of



STANDARD PARK
BUILT ELEMENTS








p.7 CITY OF PARK EV SPORTS FACILITIES SITE NO. MISC. LOCATION CONDITION MATERIALS QUANTITY BACKBOARD/HOOP FOOTBALL: FIELD LITTLE LEAGUE: SOCCER: FIELD BASKETBALL: BANGBOARD NET POLES **BACKSTOP** OUTFIELD BACKSTOP OUTFIELD SURFACE BACKSTOP OUTFIELD FENCING SURFACE INFIELD BASEBALL: INFIELD INFIELD SOFTBALL: TENNIS: COURT: OTHER FIELD:

FIELDS

COURTS



BUILDINGS

PLAYCROUNDS


BUILDINGS AND PLAYGROUNDS


ACCESS, CIRCULATION
AND PARKING

SITE NO

AND PARKIN


p.







NATURAL PARK ELEMENTS














Neighborhood: NORTH DORCHESTER Site Name: QUINCY STREET P. A. Site Type: Playet Location: QUINCY STANLEY Acreage: 0.38A


Evaluation Team: SF 3 PH


Weather Conditions: Evaluation Date: 5.7.87 Sunny Surrounding Land Uses: Residental

Site Plan



Stanley Street










View down Quincy Street showing limited visibility into park from street due to wall and fencing around edge.




Site Photograph 2

Entrance into park from Quincy Street.



Site Photograph 3

View across playground showing layout of area. Safety surface needs weeding and replenishment.







Rock outcropping adds character to site.



Site Photograph 5

Sloped grassed edge used for active free play.



Site Photograph 6

Desire line showing corner of site used as short cut.



Neighborhood: North Dorchester

Site Name: Quincy Street Play Area Location: Quincy and Stanley Streets Acreage: 0.38 A

Acreage: 0.38 A Site Type: Playlot

Site Description:

Quincy Street Play Area is a small rectangular site on the corner of Quincy and Stanley Streets. Residences abut the park on the north and west. Most of the park is a depressed area below a rock outcropping. There are concrete steps that go up, then down into the site from Quincy Street. From Stanley Street three sets of steps lead down into the park. On the outside edge of the park along the streets is a wide grass bank with two old pear trees and the rock outcropping. A playground and sitting area is located at the center of the park. Surrounding land uses are residential.


Condition Assessments:

Most standard park-built elements are in fair to good condition except for the drinking fountain and one set of steps. Although all the concrete play structures are in good condition, most of the wood and metal structures are deteriorated. The grass is in poor condition. In some areas it is most likely due to the shallow depth of soil near the rock outcropping. The trees are in good condition.

Major Site Issues:

The overall layout of Quincy Street Play Area is good. The overriding need for the park is the replacement of play structures, equipment that has greater play values, and renovation of the play surface.

Entrance into the park from Quincy Street would be more pleasant if it were at the same grade as the sidewalk. This would also facilitate maintenance of the park.



Neighborhood: North Dorchester

Site Name: <u>Quincy Street Play Area</u>
Location: <u>Quincy and Stanley Streets</u>

Acreage: 0.38 A Site Type: Playlot

No.: ND-8

Site Description:

Quincy Street Play Area is a small rectangular site on the corner of Quincy and Stanley Streets. Residences abut the park on the north and west. Most of the park is a depressed area below a rock outcropping. There are concrete steps that go up, then down into the site from Quincy Street. From Stanley Street three sets of steps lead down into the park. On the outside edge of the park along the streets is a wide grass bank with two old pear trees and the rock outcropping. A playground and sitting area is located at the center of the park. Surrounding land uses are residential.


Condition Assessments:

Most standard park built elements are in fair to good condition except for the drinking fountain and one set of steps. Although all the concrete play structures are in good condition, most of the wood and metal structures are deteriorated. The grass is in poor condition. In some areas it is most likely due to the shallow depth of soil near the rock outcropping. The trees are in good condition.

Major Site Issues:

The overall layout of Quincy Street Play Area is good. The overriding need for the park is the replacement of play structures and renovation of the play surface. The replacement of play structures should consider the use of equipment that has greater play values.

Entrance into the park from Quincy Street would be more pleasant if it were at the same grade as the sidewalk. This could be accomplished here, which would also facilitate maintenance of the park.



SITE SUMMARY




•		
DESIGN CONSIDERATIONS:		<u> </u>
LAYOUT/ORGANIZATION OF SPACE	10 1-900 - 161-1 1610 206 11 10 , 100 - 100 1	_
USE OF PLANT MATERIALS	JULY JULY 26 1 2003 142. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	11
APPROPRIATENESS OF PARK FUNCTIONS TO NEIGHBORHOOD		111
BARRIER FREE DESIGN	CHILITALISMON NO WAS SELL OF BUT BY THE BEST OF THE STATE	_
DRAINAGE CONDITION	1. (J. 1. J. 1. J. 1. J.	<u> </u>
DESIGN-RELATED MAINTENANCE ISSUES		V
VANDALISM	DIDE WARE OF THE HELLING IN	77
VACANT PARCEL TO SOUTH, EAST		_
VISIBILITY AND SAFETY:		_
VISIBILITY INTO SPACE	MEN - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -)E.
VISIBILITY OUT FROM SPACE		7.7
HIDDEN CORNERS IN SPACE	No. C	. 1
		<u>U</u>
CONDITION ASSESSMENTS:		TA
STANDARD PARK BUILT ELEMENTS	1 The second of	
SPORTS FACILITIES		
PLAYGROUNDS		
BUILDINGS		
NATURAL PARK ELEMENTS	7	
PRIMARY SITE ISSUES: Explicate Control of production of the produ	SIL A LUCY LOUIS OF THE STATE O	
	IE N	رمح



STANDARD PARK BUILT ELEMENTS







p.7 CITY OF BOSTON PARK EVALUATION SPORTS FACILITIES SITE NO. MISC. COCATION CONDITION MATERIALS UNAUTITY BACK BOARD / HOOP FOOTBALL: FIELD LITTLE LEAGUE: SOCCER: FIELD BANGBOARD BASKETBALL: NET POLES BACKSTOP OUTFIELD OUTFIELD BACKSTOP OUTFIELD BACKSTOP INFIELD FENCING SURFACE INFIELD INFIELD SURFACE SOFTBALL: BASEBALL: TENNIS: UTHEK COURT:

LIEFDS


COURTS




BUILDINGS AND PLAYGROUNDS

ACCESS, CIRCULATION AND PARKING






PLAYCROUNDS




NATURAL PARK ELEMENTS











SITE NO.


Neighborhood: NORTH DORCHESTER


Site Name: RYAN PLAY AREA Site Type: Part

Location: HARROR VIEW | DORCHESTEL Acreage: 0.64A

Evaluation Team: F 3 2# Weather Conditions: Evaluation Date: Sunni

Surrounding Land Uses: Residential Compiler:









Site Photograph 1

View of edge along Harbor View Street. Trees growing well in continuous plant bed along edge. Grass worn and poorly maintained. Trash needs pick up.




Site Photograph 2

Shelter with game tables. Play equipment behind.



Site Photograph 3

Play structures in good condition but sand level low and concrete footings exposed. Weeds need removal.








Site Photograph 4

View of corner of Dorchester and Harbor View. Mature trees define edge. Sign gives park identity, welcomes. Are two rows of fencing around park necessary?




Site Photograph 5

Short cut and access point at this corner - an erosion problem.



Site Photograph 6

Sand level too low, exposed concrete footings.



Neighborhood: North Dorchester

Site Name: Ryan Play Area

Location: Harbor View Street and Dorchester Avenue

Acreage: 0.64 A Site Type: Playlot

A Principal

Site Description:

Ryan Play Area is a small trapezoidal site on the corner of Dorchester Avenue and Harbor View Street. Residential and commercial use abuts it on the north and east. The park is elevated above the streets and is framed by sloping strips of grass with trees along the road sides. The park is reached by two sets of stairs. The entire interior of the park is paved except for five small areas with sand for play structures. A basketball court is located in the northeast corner of the site as well as a spray pool area. The remainder of the park is laid out with benches and play structures. An open-air shelter is located near Harbor View Street.

Condition Assessments:

All standard park-built elements are in fair to good condition except for one light which is vandalized and inoperable, and some sections of fence which need repair. The basketball court is in fair condition. The playground equipment is in good condition. Some of the curbs need resetting and all sand areas need additional sand. Renovations to the park are scheduled by the City.

Major Site Issues:

Ryan Play Area does not appear to be vandalized, and has aged well since its original construction in 1962. Although all facilities are in good working order, the playground would serve children better with play equipment that encouraged more varied and interactive play. The site would be greatly enhanced with new plantings and refurbished benches.

The slope down to the sidewalk along Dorchester Avenue and most of Harbor View Street is too steep for easy maintenance. Extension of the existing puddingstone wall along these edges would not only facilitate maintenance but would make the park more attractive.



Neighborhood: North Dorchester Site Name: Rvan Play Area

Location: Harbor View Street and Dorchester Avenue

Acreage: 0.64 A Site Type: Playlot

Site Description:

Ryan Play Area is a small trapezoidal site on the corner of Dorchester Avenue and Harbor View Street. Residential and commercial use abuts it on the north and east. The park is elevated above the streets and is framed by sloping strips of grass with trees along the road sides. The park is reached by two sets of stairs. The entire interior of the park is paved except for five small areas with sand for play structures. A basketball court is located in the northeast corner of the site as well as a spray pool area. The remainder of the park is laid out with benches and play structures. An open-air shelter is located near Harbor View Street.

No.: ND-9


Condition Assessments:

All standard park built elements are in fair to good condition except for one light which is vandalized and inoperable and some sections of fence which need repair. The basketball court is in fair condition. The playground equipment is in good condition. Some of the curbs need resetting and all sand areas need additional sand. Renovations to the park are scheduled by the City.

Major Site Issues:

Ryan Play Area does not appear to be vandalized, and has aged well since its original construction in 1962. Although all facilities are in good working order, the playground would serve children better with play equipment that encouraged more varied and interactive play. The site would be greatly enhanced with new plantings and refurbishing of benches.


The slope down to the sidewalk along Dorchester Avenue and most of Harbor View Street is too steep for easy maintenance. Extension of the existing puddingstone wall along these edges would not only facilitate maintenance but would make the park more attractive as well.



CITY OF BOSTON





	PARK EVALUATION														SITE SUMMARY							(ND 9)				
)					1	Y						-					L									SI	TE N	Ю.
20 1400 to 14 10 15 10 10	14 1 1 200 1 11 11 11 11 11 11 11 11 11 11 11 11	the second of the latter of the second of th			an of proportional popular from an area	1. Car & Shall	Wind Double to Spord in the internal of their de	- Since a mind with					,			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1.16.16.100	the particularity of the second		The property of the property o	-	The second secon			State of the state)		
	- 1				1.	1,	مي ديرا		3		-								-	-		`						
	ESIGN CONSIDERATIONS:	LAYOUT/ORGANIZATION OF SPACE (T	USE OF PLANT MATERIALS	APPROPRIATENESS OF PARK FUNCTIONS TO NEIGHBORHOOD	BARRIER FREE DESIGN	DRAINAGE CONDITION	DESIGN-RELATED TO THE MAINTENANCE ISSUES	VANDALISM	ACANT PARCEL TO SOUTH, EAST	ISIBILITY AND SAFETY:	VISIBILITY INTO SPACE	VISIBILITY OUT FROM SPACE	HIDDEN CORNERS IN SPACE		ONDITION ASSESSMENTS:	STANDARD PARK BUILT ELEMENTS	SPORTS FACILITIES	PLAYGROUNDS	BUILDINGS	NATURAL PARK ELEMENTS	RIMARY SITE ISSUES:	9 1						= -




STANDARD PARE.
BUILT ELEMENTS














BUILDINGS AND p. PLAYGROUNDS CITY OF BOSTON PARK EVALUATION ACCESS, CIRCULATION AND PARKING SITE NO. MISC. PARKING LOCATION ACCESS CONDITION ame play aver len RGANIZATION 250.00 MATERIALS carbonel 1011ling CA 101 1 CUANTITY 2 concret Pipes EQUIPMENT: 5 Convete anim 5 Metal climbing *EDESTRIAN CIRCULATION EHICULAR CIRCULATION PLAYGROUNDS (GENERAL) 1:1669 5011 MAINTENANCE ACCESS EDESTRIAN ACCESS AGE DISTRIBUTION: VEHICULAR ACCESS ACCESS CONTROL: RECREATION RESTROOM FENCING STORAGE SURFACE EDGING OTHER PLAYGROUNDS



NATURAL PARK ELEMENTS











Surrounding Land Uses:




197.3


Neighborhood: North Dorchester
Site Name: Sayin Hill Park
Location: Grampian Way! Appine
Evaluation Team: 57787

Site Type: Multi-Purpose Park
Acreage: 8.24A

Weather Conditions:
Summ

Site Plan









Site Photograph 1

Stone step access from Caspian Way.




Site Photograph 2

Panoramic view from high point of park showing Neponset Bay.



Site Photograph 3

Typical character of terrain in center of park. Wheels of dirt bikes eroding surface.





No curb along Grampian
Way - cars parking under
trees and compacting
soil in tree root
zone.




Site Photograph 5

View into site showing rock outcrops and mature trees as outstanding scenic features.



Site Photograph 6


Basketball court and tennis court located on level area at edge of park. Mature shade trees define edge and provide shade.







Entrance from Grampian Way to tennis courts.




Site Photograph 8

Trash and litter build-up at back of courts.



Site Photograph 9

Informal walkway around site.








Alpine Way once paved, but now very overgrown. Has potential of being important supervision access through site.




Site Photograph 11

Erosion of pathway due to over use.



Site Photograph 12

Slide - exposed concrete footing and loose metal at left end of slide both safety hazards.



Neighborhood: North Dorchester

Site Name: Savin Hill Park

Location: Grampian and Alpine Ways

Acreage: 8.26 A Site Type: Playfield

Site Description:

Savin Hill Park is an extraordinary landscape park prominently located at the high point of Savin Hill. Grampian Way, Caspian Way and Alpine Way (a dirt road) encompass the site. There are residences along the north edge. From its rocky summit are magnificent views to the south and east over the Neponset River Estuary, harbor islands, and Quincy. The landscape of the summit is composed of puddingstone outcroppings interspersed with grass meadows. Gnarled stunted trees grow in rock crevices. On the lower slopes there are enormous oaks. Shrubs and small trees grow along the south and west hillsides and behind adjacent residences along the north edge of the park.


Tennis and basketball courts and a few play structures are located along Grampian Way. Granite and puddingstone stairs are constructed in a naturalistic manner to provide easy access up the steeply sloping rock outcroppings.

Condition Assessments:

The standard park-built elements and sports facilities are all in fair to good condition. The play structures are also in fair to good condition, but no safety surface is present. The trees are mostly in good condition.

Major Site Issues:

Savin Hill Park is a spectacular landscape park with beautiful long distance views. However, inappropriate uses including drinking, riding of dirt bikes, setting of fires and writing of graffit has greatly eroded the appearance of this special site. The parkland is also being used for parking of cars, which should be prevented. This use and the previously mentioned abuse combines with insufficient maintenance to cause deterioration. Increased maintenance effort should focus on trash removal and lawn and tree maintenance. Additional plantings suitable for the dry and exposed site and organization of circulation with careful attention to how slopes should be ascended, would improve the use and appearance of the park.





No.: ND-10

Neighborhood: North Dorchester Site Name: Savin Hill Park

Location: Grampian and Alpine Ways

Acreage: 8.26 A Site Type: Playfield

Site Description:

Savin Hill Park is an extraordinary landscape park prominently located at the high point of Savin Hill. Grampian Way, Caspian Way and Alpine Way (a dirt road) encompass the site. There are residences along the north edge. From its rocky summit are magnificent views to the south and east over the Neponset River Estuary, harbor islands and Quincy. The landscape of the summit is composed of puddingstone outcroppings interspersed with grass meadows. Gnarled stunted trees grow in rock crevices. On the lower slopes there are enormous oaks. Shrubs and small trees grow along the south and west hillsides and behind adjacent residences along the north edge of the park.


Tennis and basketball courts and a few play structures are located along Grampian Way. Granite and puddingstone stairs are constructed in a naturalistic manner to provide easy access up the steeply sloping rock outcroppings.

Condition Assessments:

The standard park built elements and sports facilities are all in fair to good condition. The play structures are also in fair to good condition, however, no safety surface is present. The trees are mostly in good condition.

Major Site Issues:

Savin Hill Park is a spectacular landscape park with beautiful long distance views. However, inappropriate uses including drinking, riding of dirt bikes, setting of fires and writing of graffiti has greatly eroded the appearance of this special site. The parkland is also being used for parking of cars, which should be prevented. This use and the previously mentioned abuse combines with insufficient maintenance to cause deterioration. Increased maintenance effort should focus on trash removal and lawn and tree maintenance. The park would greatly benefit from the development of a management plan. Additional plantings suitable for the dry and exposed site and organization of circulation with careful attention to how slopes should be ascended, would improve the use and appearance of the park.



DESIGN CONSIDERATIONS:


CONDITION ASSESSMENTS:

PRIMARY SITE ISSUES:


VACANT PARCEL TO SOUTH,


VISIBILITY AND SAFETY:

H



CITY OF BOSTON PARK EVALUATION p.0 STANDARD PARK BUILT ELEMENTS SITE NO. MISC. LOCATION CONDITION MATERIALS UANTITY DRINKING FOUNTAINS PARKING/ROAL WATER FEATURES BENCHES, PARK BICYCLE RACKS PEDESTRIAN: PICNIC TABLES SERVICE GATES TRASH RECEPTACLES: SIGNS, ENTRY CATCHBASINS GAME TABLES BLEACHERS DUMPSTERS MONUMENTS BOLLARDS LIGHTING SPORTS RAILINGS FENCES CURBS STAIRS RAMPS OTHER WALLS








BUILDINGS AND CITY OF BOSTON PARK EVALUATION PLAYGROUNDS CIRCULATION ACCESS, AND PARKING SITE NO. MISC. PARKING LOCATION ACCESS CONDITION RGANIZATION MATERIALS MATERIALS Laur mark CUANTITY menone EDESTRIAN CIRCULATION PEHICULAR CIRCULATION (GENERAL) St. A. ACCESS CONTROL: 1/64 IAINTENANCE ACCESS PEDESTRIAN ACCESS AGE DISTRIBUTION: VEHICULAR ACCESS PLAYGROUNDS SQUIPMENT: RECREATION RESTROOM FENCING STORAGE SURFACE EDGING OTHER CIRCULATION VAD CCESS' PLAYGROUNDS





CITY OF BOSTON PARK EVALUATION

NATURAL PARK ELEMENTS













CITY OF BOSTON PARK EVALUATION




Neighborhood: North Doechester Site Name: COPPENS SQUARE Site Type: Salave Location: BONDOIN, ADAMS & CHURCH Acreage: 0.3A Evaluation Team:ムチストオー Weather Conditions: Evaluation Date: 5.7.87 unny Surrounding Land Uses: Residental abush Flicale House

Site Plan









View from Adams Street showing mature trees and shrubs and fountain as focal point.



Site Photograph 2

Flowering and evergreen shrubs in need of restoration. Cars parked around edges detract from impact of square as an important green space.



Site Photograph 3

Benches located near bus stop. Grass on this corner worn away.







Pedestrian circulation has worn grass along Bowdoin Street. Sidewalk needed.




Site Photograph 5

Mature Beech tree contributes to this square. Tree is being inappropriately used for a rope swing. Bare grass patches at base of benches.



Site Photograph 6

Trees and shrubs need renovative pruning. Grass needs improved mowing around base of trees and edges of shrub beds.



Neighborhood: North Dorchester

Site Name: Coppens Square

Location: Bowdoin and Adams Streets

Acreage: 0.3 A Site Type: Square

Site Description:

Coppens Square is a triangular site prominently located at the center of the intersection of Bowdoin, Adams and Church Streets. The park is elevated above Bowdoin and Adams Streets. There is a large fountain at the center of the site with several benches near it. Large shrub plantings, now quite overgrown, are prominently located at each corner of the park. A large purple beech, crab apples and evergreen trees are located around the edges of the park.

There is only one sidewalk for passage along Bowdoin Street, and there are several worn paths along Adams and Church Streets. Surrounding land uses are residential and institutional.

Condition Assessments:


All standard park-built elements are in fair to good condition. The fountain is in good condition, with some graffiti. The trees are mostly in good condition, although the beech tree has been badly carved and many trees have been used for rope swings. The shrub plantings are overgrown, and many trees have seeded themselves into the shrub beds. The lawn is mostly in good condition, although badly worn in several areas because of the lack of paved pathways.

Major Site Issues:

Coppens Square serves as an important green space for the area. Its elevation above the street and its vegetative cover which screens views of traffic help to create a pleasant sitting space. However, vandalism and lack of maintenance have contributed to the deterioration and shabby appearance of the park. Shrubs are overgrown and need restoration. Use of the trees for swings is inappropriate and indicates a need for a nearby play area.

Circulation needs to be studied and additional paths installed. Lack of paved paths along Adams and Church Streets, as well as within the site, has resulted in many worn areas. A simple path system around the fountain and responding to entry points would greatly improve the use and appearance of the park. Installations of paths should be done carefully to avoid damage to tree roots, particularly of the specimen beech.

The fountain does not operate at present, and since it forms the focal point of the space it should be reactivated.



Dior il

No.: ND-15

Neighborhood: North Dorchester

Site Name: Coppens Square

Location: Bowdoin and Adams Streets

Acreage: 0.3 A Site Type: Square

Site Description:

Coppens Square is a triangular site prominently located at the center of the intersection of Bowdoin, Adams and Church Streets. The park is elevated above Bowdoin and Adams Streets. There is a large fountain at the center of the site with several benches near it. Large shrub plantings, now quite overgrown, are prominently located at each corner of the park. A large purple beech, crabapples and evergreen trees are located around the edges of the park.

There is only one sidewalk for passage along Bowdoin Street, and there are several worn paths along Adams and Church Streets. Surrounding land uses are residential and institutional.


Condition Assessments:

All standard park built elements are in fair to good condition. The fountain is in good condition, with some graffiti. The trees are mostly in good condition, although the beech tree has been badly carved and many trees have been used for rope swings. The shrub plantings are overgrown, and many trees have seeded themselves into the shrub beds. The lawn is mostly in good condition, although badly worn in several areas because of the lack of paved pathways.

Major Site Issues:

Coppens Square serves as an important green space for the area. Its elevation above the street and its vegetative cover which screens views of traffic help to create a pleasant sitting space. However, vandalism and lack of maintenance have contributed to the deterioration and shabby appearance of the park. Shrubs are overgrown and need restoration. Use of the trees for swings is inappropriate and indicates a need for a nearby play area.

Circulation needs to be studied and additional paths installed. Iack of paved paths along Adams and Church Streets, as well as within the site, has resulted in many worn areas. A simple path system around the fountain and responding to entry points would greatly improve the use and appearance of the park. Installations of paths should be done carefully to avoid damage to tree roots, particularly of the specimen beech.



DRATT

The fountain does not operate at present, and since it forms the focal point of the space it should be reactivated.



EVALUATION PARK

Manutain as autr, as paid mind, Should blanting as ands Howeming hoes & beach trace set in buin. Simple good

dagn. Sidewall on she and only. Weeked all airons

LAYOUT/ORGANIZATION OF SPACE

DESIGN CONSIDERATIONS:

APPROPRIATENESS OF PARK FUNCTIONS TO NEIGHBORHOOD

BARRIER FREE DESIGN DRAINAGE CONDITION DESIGN-RELATED MAINTENANCE ISSUES

USE OF PLANT MATERIALS

SITE SUMMARY

redograticizates another of ladues hat or cinc. pade - wom gass CARCULATION NEEDS Should be should be addressed and addressed processed in the falled showing anagement here removation, moet haso prime, Visibility in and out if space blocked by oversion to regular head words.

Showns head verwather and have detworated the spirit curbent on one comen of sidewalk on one side only Beech the leurs ved for vopic sinny - Inchestes vece it graph, lower henches, lower has turbs vencines and tourisain good to fain spurpher almost specific seguste

STANDARD PARK BUILT ELEMENTS

SPORTS FACILITIES PLAYGROUNDS

CONDITION ASSESSMENTS:

NATURAL PARK ELEMENTS

BUILDINGS

PRIMARY SITE ISSUES;

EAST

VACANT PARCEL TO SOUTH,

VANDALISM

VISIBILITY OUT FROM SPACE

VISIBILITY INTO SPACE

VISIBILITY AND SAFETY:

HIDDEN CORNERS IN SPACE

a lad larting around trained black view of detact from inject of



CITY OF BOSTON PARK EVALUATION p.6 STANDARD PARK BUILT ELEMENTS SITE NO. MISC. sale Icpay LOCATION CONDITION MATERIALS QUANTITY. WATER FEATURES Form part DRINKING FOUNTAINS PARKING/ROAD: BENCHES, PARK BICYCLE RACKS PEDESTRIAN: PICNIC TABLES SERVICE GATES TRASH RECEPTACLES: SIGNS, ENTRY CATCHBASINS GAME TABLES BLEACHERS DUMPSTERS MONUMENTS

LIGHTING

FENCES

SPORTS

RAILINGS

RAMPS


STAIRS

WALLS


OTHER

BOLLARDS


CURBS



p.7 CITY OF BOSTON PARK EVALUATION SPORTS FACILITIES SITE NO. MISC. LOCATION CONDITION MATERIALS QUANTITY BACKBOARD/HOOP FOOTBALL: FIELD LITTLE LEAGUE: SOCCER: FIELD BASKETBALL: BANGBOARD NET POLES BACKSTOP OUTFIELD BACKSTOP OUTFIELD BACKSTOP OUTFIELD FENCING SURFACE INFIELD INFIELD INFIELD SURFACE BASEBALL: SOFTBALL: OTHER OTHER THER OTHER TENNIS: COURTS FIELDS



BUILDINGS AND PLAYGROUNDS CITY OF BOSTON PARK EVALUATION ACCESS, CIRCULATION AND PARKING SITE NO PARKING LOCATION ACCESS CONDITION RGANIZATION MATERIALS MATERIALS CUANTITY EDESTRIAN CIRCULATION ACCESS CONTROL: CLUY 6 .. VEHICULAR CIRCULATION (GENERAL) MAINTENANCE ACCESS PEDESTRIAN ACCESS AGE DISTRIBUTION: JEHICULAR ACCESS LAYGROUNDS RECREATION SQUIPMENT: RESTROOM STORAGE SURFACE FENCING EDGING DTHER CIRCULATION CCESS, BUILDINGS PLAYGROUNDS



CITY OF BOSTON PARK EVALUATION

NATURAL PARK ELEMENTS



